




Do not remove until final code inspection. Save label for future reference.

ENERGY STAR® Certified in Highlighted Regions
Certifié ENERGY STAR dans les régions en surbrillance

Canada
 energystar.gc.ca



U.S. / É.U.
 energystar.gov



ER/RE 15

DO NOT REMOVE UNTIL FINAL INSPECTION/NE PAS RETIRER AVANT L'INSPECTION FINALE



Renewal by Andersen
 WINDOW REPLACEMENT an Andersen Company

AND-N-29-00809-00001
 Vinyl/Wood Composite Material
 Dual-Pane with Argon
 Product Type: Double Hung

ENERGY PERFORMANCE RATINGS

U-Factor 0.28 (U.S./I-P)	1.59 (Metric/SI)	Solar Heat Gain Coefficient 0.19
---------------------------------------	----------------------------	--

ADDITIONAL PERFORMANCE RATINGS

Visible Transmittance 0.42	-
--------------------------------------	---

Manufacturer stipulates that these ratings conform to applicable NFRC procedures for determining whole product performance. NFRC ratings are determined for a fixed set of environmental conditions and a specific product size. NFRC does not recommend any product and does not warrant the suitability of any product for any specific use. Consult manufacturer's literature for other product performance information.
 www.nfrc.org



Licensee: 129-H-836
 Andersen Corporation
 RbA Double-Hung


Manufacturer stipulates certification to the applicable standards.

STANDARD	RATING
AAHA/WDMA/CSA 101/I.S.2/A440-08	Class LC-PG25; Size Tested: 45.0 inx 77.01 DP +35/-35
AAHA/WDMA/CSA 101/I.S.2/A440-11	LC-PG25; 45.0 inx 77.01in +35/-35
AAHA/WDMA/CSA 101/I.S.2/A440-08 A440S1-09	Class LC-PG25



201A Front triple Double Hung

Window - 24.00W x 61.00H



EXTERIOR

360°


INTERIOR

TILT
TO CLEAN



201A Front triple Double Hung

Window - 24.00W x 61.00H



EXTERIOR

360°

INTERIOR

TILT
TO CLEAN



Left + Right + Window

